

Product Availability and Markings

Shamir Computer™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking
Hard Resin	1.498	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Clear	14mm	15 FFC TR ⑤ ⑤ 14
Transitions®	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Gray & Brown	14mm	⑤ FFC 14
Transitions® XTRActive™	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Gray	14mm	X5 ⑤ FFC 14
DLC™ (Trivex)	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Clear	14mm	TX ⑤ FFC 14
DLC™ (Trivex) Transitions®	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Gray & Brown	14mm	TTX ⑤ FFC 14
DLC™ (Trivex) Transitions® XTRActive™	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Gray	14mm	XX ⑤ FFC 14
1.56	1.56	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Clear	14mm	56 ⑤ FFC 14
Polycarbonate	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Clear	14mm	PC ⑤ FFC 14
Polycarbonate Transitions®	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray & Brown	14mm	PT ⑤ FFC 14
Polycarbonate Transitions® XTRActive™	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray	14mm	PX ⑤ FFC 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

Product Availability and Markings

Shamir Computer™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking	
Superlite™ 1.6	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Clear	14mm	16 S FFC	S 14
Superlite 1.6 Transitions®	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray & Brown	14mm	T6 S FFC	S 14
Superlite 1.6 Transitions® XTRActive™	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray	14mm	X6 S FFC	S 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

Product Availability and Markings

Shamir WorkSpace™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking
Hard Resin	1.498	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Clear	14mm	15 Ⓢ FFW 14
Transitions®	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Gray & Brown	14mm	TR Ⓢ FFW 14
Transitions® XTRActive™	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Gray	14mm	X5 Ⓢ FFW 14
DLC™ (Trivex)	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Clear	14mm	TX Ⓢ FFW 14
DLC™ (Trivex) Transitions®	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Gray & Brown	14mm	TTX Ⓢ FFW 14
DLC™ (Trivex) Transitions® XTRActive™	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Gray	14mm	XX Ⓢ FFW 14
1.56	1.56	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Clear	14mm	56 Ⓢ FFW 14
Polycarbonate	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.50	Clear	14mm	PC Ⓢ FFW 14
Polycarbonate Transitions®	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.50	Gray & Brown	14mm	PT Ⓢ FFW 14
Polycarbonate Transitions® XTRActive™	1.586	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.50	Gray	14mm	PX Ⓢ FFW 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

Product Availability and Markings

Shamir WorkSpace™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking	
Superlite™ 1.6	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Clear	14mm	16 S FFC	S 14
Superlite 1.6 Transitions®	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray & Brown	14mm	T6 S FFC	S 14
Superlite 1.6 Transitions® XTRActive™	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray	14mm	X6 S FFC	S 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®